SO3-000139D

INDUSTRIAL STORMWATER GENERAL PERMIT DISCHARGE MONITORING REPORT

MONITORING PERIOD	year		eb/Mar Apr/N			
Alaskan Copper Works Location: 3200 6th AV County: KING You must send a Discisuspended sampling		3443 t (DMR) to Ectainment of ber	ALASKA COPP PO BOX 3546 SEATTLE WA ology every qu ochmark values	98124-3546 arter. If there	SS CO e was no disc l	
Discharge Point						
	qualifying storm even	t this quarter	so no values a	re entered be	elow (see exp	olanation)
Quarterly Monitoring		AVERAGE	MAXIMUM	UNITS	Sample Type	Events Sampled
Turbidity	Consistent Attainment		26.0	NTU	Grab	1
pН	Consistent Attainment		6.89	Standard Unit	Grab	1
Zinc (total)	Consistent Attainment		143	ug/L	Grab	1
Oil & Grease	Consistent Attainment		3.37	mg/L	Grab	1
Copper	Consistent Attainment		146	ug/L	Grab	1
Lead	Consistent Attainment		25.3	ug/L	Grab	1
Hardness	Consistent Attainment		15	mg/L	Grab	1 .
Total Suspended Solids	Consistent Attainment		60	mg/L	Grab	1
AND COMPLETE. I AM AWARE	F LAW THAT I HAVE PERSONALLY E LS IMMEDIATELY RESPONSIBLE FO THAT THERE ARE SIGNIFICANT PE 1001 AND 33 USC § 1319. (PENALTIES 'E YEARS.)	NALTIES FOR SUBMIT	TING FALSE INFORMA	TION INCLUDING TI	HE POSSIBILITY OF F	UE, ACCURATE, INE AND
James	Brown	OR PRINTED)		1/28/10		
NAME/TITLE/PRINC	(b) (6) TELEPHONE NUMBER					
turbidity, zinc, copper, a various buildings at the zinc and copper. Alask readings. Alaskan Cop	eted a Level One Response and TSS. The source invest Alaskan Copper facility. The an Copper is also evaluating the process of present of Ecology when it is	stigation included the analytical tes ng whether back paring a Level T	d collection of roo ting results indica up in City of Seat	of drain samples ated that the ro- ttle storm drains	s on December ofs appear to be s is affecting TS	15, 2009 from a source of S and turbidity